


LOW TEMP FOAM GUN

- Install wire stand.
- Insert 1/2" Low Temp Glue Sticks (ST1446) in tunnel at rear of gun.
- Preheat approximately 5 minutes before using.
- To release glue, pull trigger; release trigger to stop flow.



Bonds to:

- Foam
- Wood
- Paper
- Foil
- Many other craft materials

CAUTION:

Do not touch nozzle or melted glue.
Operating temperature of gun is 230° F.
Do not use Low Temp Glue Stick if finished product may be exposed to temperatures of 130° F.

Woodland Scenics
P.O. Box 98
Linn Creek, MO 65052
U.S.A.
© 1998 OCO

Made in Taiwan

